



**June and Ken Bourke Farm Buildings Case Study,
Knappagh, Westport, Co. Mayo GLAS TFB 2016**

Áine Doyle MUBC Conservation Consultant











Hen House

- Vegetation/ivy damage to stonework and corrugated iron roof sheeting
- Large overhanging branches to rear
- Extensive pointing loss to walls
- Decay of timber door lintel
- Timber window repairs required












Hen House after works









Former Dwelling House

- Large overhanging branches and ivy damage to rear gable
- Roof held down with concrete blocks
- Large number of holes in corrugated sheeting on garden side
- Gutters in poor condition, downpipe missing













Former Dwelling House after works





Wool Dying Shed

- Roof timbers in poor condition
- Corrugated iron held on with concrete blocks
- Gutters in poor condition and downpipe missing
- Isolated repointing required on rear side















Wool Dying Shed after works







Turf Shed

- Large tree breaking down apex of gable nearest house
- Ivy growing on other gable
- Corrugated sheeting held down with concrete blocks
- Extensive loss of mortar from joints























